

不快指数

別表

気温(°C)	湿度(%)												
	90	85	80	75	70	65	60	55	50	45	40	35	30
32	88	87	86	85	84	84	83	82	81	80	79	78	77
31	86	85	85	84	83	82	81	80	80	79	78	77	76
30	84	84	83	82	81	81	80	79	78	78	77	76	75
29	83	82	81	81	80	79	78	78	77	76	76	75	74
28	81	80	80	79	78	78	77	76	76	75	74	74	73
27	79	79	78	77	77	76	76	75	74	74	73	73	72
26	78	77	77	76	75	75	74	74	73	73	72	71	71
25	76	75	75	74	74	73	73	72	72	71	71	70	70
24	74	74	73	73	72	72	71	71	70	70	70	69	69

60~64	何も感じない	
65~69	快い	
70~74	暑くない	
75~79	やや暑い	75を超えると1割が不快を感じる
80~84	暑くて汗が出る	80を超えると全員が不快を感じる
85~	暑くてたまらない	